



Intel® 82443GX Specification Update

November 1998

Order Number: 290643-002

The Intel 82443GX may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are documented in this Specification Update.

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications.

Intel may make changes to specifications and product descriptions at any time, without notice.

Designers must not rely on the absence or characteristics of any features or instructions marked "reserved" or "undefined." Intel reserves these for future definition and shall have no responsibility whatsoever for conflicts or incompatibilities arising from future changes to them.

The Intel 82443GX may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Contact your local Intel sales office or your distributor to obtain the latest specifications and before placing your product order.

Copies of documents which have an ordering number and are referenced in this document, or other Intel literature, may be obtained from:

Intel Corporation

or call 1-800-548-4725
or visit Intel's website at <http://www.intel.com>

Copyright © Intel Corporation 1998.

* Third-party brands and names are the property of their respective owners.



CONTENTS

REVISION HISTORY	v
PREFACE	vi
Specification Update for 82443GX AGPset	
GENERAL INFORMATION	9
SPECIFICATION CHANGES	11
ERRATA.....	17
SPECIFICATION CLARIFICATIONS.....	18
DOCUMENTATION CHANGES	19



REVISION HISTORY

INTEL 82443GX

Date of Revision	Version	Description
October 1998	-001	Initial Release.
November 1998	-002	1. Added Specification Change 5: Modify Memory Buffer Strength Terminology in Register 69-6Eh.

PREFACE

This document is an update to the specifications contained in the Intel® 440GX AGPset: 82443GX Host Bridge/Controller Datasheet, Order No. 290638-001, and contains issues affecting all designs using the Intel 82443GX.

This document is intended for hardware system manufactures and software developers of applications, operating systems or tools. It contains Specification Changes, Errata, Specification Clarifications, and Documentation Changes.

Nomenclature

Specification Changes are modifications to the current published specifications. These changes will be incorporated in the next release of the specifications.

Errata are design defects or errors. Errata may cause the Intel® 82443GX, behavior to deviate from published specifications. Hardware and software designed to be used with any given stepping must assume that all errata documented for that stepping are present on all devices.

Specification Clarifications describe a specification in greater detail or further highlight a specification's impact to a complex design situation. These clarifications will be incorporated in the next release of the specifications.

Documentation Changes include typos, errors, or omissions from the current published specifications. These changes will be incorporated in the next release of the specifications.

Component Identification via Programming Interface

The Intel 82443GX stepping can be identified by the following register contents:

82443GX Stepping	Vendor ID ¹	Device ID ²	Revision Number ³
A-0	8086h	71A0/71A2h	00h

NOTES:

1. The Vendor ID corresponds to bits 15-0 of the Vendor ID Register located at offset 00-01h in the PCI function 0 configuration space.
2. The Device ID corresponds to bits 15-0 of the Device ID Register located at offset 02-03h in the PCI function 0 configuration space.
3. The Revision Number correspond to bits 7-0 of the Revision ID Register located at offset 08h in the PCI function 0 configuration space.

Specification Update for Intel® 82443GX



GENERAL INFORMATION

This section covers the Intel 82443GX.

INTEL 82443GX COMPONENT MARKING INFORMATION

Stepping	S-Spec	Top Marking	Notes
A-0		FW82443GX Q633ES	Engineering Sample, FM Test
A-0		FW82443GX Q634ES	Engineering Sample, T03 Test
A-0	SL2TF	FW82443GX SL2TF	443GX A-0 Production ASSY
A-0	SL2VJ	FW82443GX SL2VJ	443GX A-0 Production ASSY

Summary Table of Changes

The following table indicates the Specification Changes, Errata, Specification Clarifications or Documentation Changes, which apply to the listed 82443GX Steppings. Intel intends to fix some of the errata in a future stepping of the component, and to account for the other outstanding issues through documentation or Specification Changes as noted. This table uses the following notations:

CODES USED IN SUMMARY TABLE

X:	Erratum, Specification Change or Clarification that applies to this stepping.
Doc:	Document change or update that will be implemented.
Fix:	This erratum is intended to be fixed in a future stepping of the component.
Fixed:	This erratum has been previously fixed.
NoFix	There are no plans to fix this erratum.
(No mark) or (Blank Box):	This erratum is fixed in listed stepping or specification change does not apply to listed stepping.
Shaded:	This item is either new or modified from the previous version of the document.

82443GX

NO.	A0	Plans	SPECIFICATION CHANGES
1	x	Doc	Modify Abort Disable Test Mode Configuration Bits in Register F4h [30:29]
2	X	Doc	Modify MD[63:0] [Control2] and MECC [7:0] [Control 1] bits in Register CA-CCh [20,17]
3	X	Doc	Non-Supported SDRAM Memory Configuration
4	X	Doc	Modify Input/Output Data Mask A/B-Side Data Buffer Strength Programming in Register CA-CCh [6:2]
5	X	Doc	Modify Memory Buffer Strength Terminology in Register 69-6Eh

NO.	A0	Plans	ERRATA
1	X	NoFix	SDRAM Suspend Refresh
NO.	A0	Plans	SPECIFICATION CLARIFICATIONS
1	X	Doc	CKE Function with Registered DIMMs
2	X	Doc	Memory Initialization with ECC Enabled
3	X	Doc	Normal Refresh Enable
4	X	Doc	DCLKO State During POS/STR
NO.	A0	Plans	DOCUMENTATION CHANGES
1	X	Doc	Correction to the 82443GX Alphabetical BGA Pin List (Table 5-1)



Intel® 82443GX SPECIFICATION CHANGES

1. **Modify Abort Disable Test Mode Configuration Bits in Register F4h [30:29]**

Intel Reserved Register bits at offset F4h, bits 29 and 30 should be set to 1 for normal operation.

2. **Modify MD[63:0] [Control2] and MECC [7:0] [Control 1] bits in Register CA-CCh [20,17]**

Reserved programming of bits 20 and 17 of register CA-CCh are valid buffer programming options. These two bits can be programming to 0 for 100MHz A and 1 for 100MHz B, as shown below:

Bits	Description
20	MD [63:0] [Control 2] This bit enables 100Mhz buffers for MD [63:0] [Control 2] . (Refer to the corresponding MBSC register for programming details). 0 100MHz A 1 100MHz B

Bits	Description
17	MECC [7:0] [Control 1] This bit enables either 100Mhz buffers for MECC [7:0] [Control 1] (Refer to the corresponding MBSC register for programming details). 0 100MHz A 1 100MHz B

3. **Non-Supported SDRAM Memory Configuration**

Any memory configuration using SDRAM memory of the type 128Mbit 32Mx4 with 13 rows and 10 columns is not supported by the 82443GX. This support has been removed because these SDRAM (13x10 128Mbit) devices are not planned for production by memory vendors.

4. *Modify Input/Output Data Mask A/B-Side Data Buffer Strength Programming in Register CA-CCh [6:2]*

Characterization of the Input/Output Data Mask A/B-Side Data buffers has shown that the actual buffers are stronger than the simulated buffer strengths. As a result, new buffer strength settings are recommended in order to improve system noise margin, as shown below:

Bits	Description
6	<p>DQMA5. This bit enables 100MHz buffers for DQMA5.</p> <p>0 100MHz A</p> <p>1 100MHz B</p>
5	<p>DQMA1. This bit enables 100MHz buffers for DQMA1.</p> <p>0 100MHz A</p> <p>1 100MHz B</p>
4	<p>DQMB5. This bit enables 100MHz buffers for DQMB5.</p> <p>0 100MHz A</p> <p>1 100MHz B</p>
3	<p>DQMB1. This bit enables 100MHz buffers for DQMB1.</p> <p>0 100MHz A</p> <p>1 100MHz B</p>
2	<p>DQMA[7:6,4:2,0]. This bit enables 100MHz buffers for DQMA[7:6], DQMA[4:2], and DQMA[0].</p> <p>0 100MHz A</p> <p>1 100MHz B</p>

5. **Modify Memory Buffer Strength Terminology in Register 69-6Eh.**

Previous changes to Register CA-CCh (for example, Specification Changes 2 and 4 above) require similar changes to Register 69-6Eh. As a result, Register 69-6Eh bit changes are shown below. These bit changes match the “100MHz A” and “100MHz B” terminology found in Register CA-CCh.

35:34	<p>MD [63:0] Buffer Strength Control 2</p> <p>4 DIMM FET Configuration: This field sets the buffer strength for the MD[63:0] path that is connected to DIMM2 and DIMM3. The buffer strength is programmable based upon the SDRAM load in detected in DIMM slots 2&3. This path is enabled when FENA is asserted (High) by the 82443GX.</p> <p>4 DIMM non-FET Configuration: This field should be programmed to the same value as MD[63:0] Buffer Strength Control 1. This buffer strength is programmable based upon the SDRAM load detected in all DIMM connectors.</p> <table border="0" style="margin-left: 40px;"> <thead> <tr> <th style="text-align: left;"><u>Value</u></th> <th style="text-align: left;"><u>Buffer Strength</u></th> </tr> </thead> <tbody> <tr> <td>00</td> <td>1X A and B</td> </tr> <tr> <td>01</td> <td>Reserved Invalid setting</td> </tr> <tr> <td>10</td> <td>2X A and B</td> </tr> <tr> <td>11</td> <td>3X B only</td> </tr> </tbody> </table>	<u>Value</u>	<u>Buffer Strength</u>	00	1X A and B	01	Reserved Invalid setting	10	2X A and B	11	3X B only
<u>Value</u>	<u>Buffer Strength</u>										
00	1X A and B										
01	Reserved Invalid setting										
10	2X A and B										
11	3X B only										
33:32	<p>MD [63:0] Buffer Strength Control 1</p> <p>4 DIMM FET Configuration: This field sets the buffer strength for the MD[63:0] path that is connected to DIMM0 and DIMM1. The buffer strength is programmable based upon the SDRAM load in detected in DIMM slots 0&1. This path is enabled when FENA is de-asserted (Low) by the 82443GX.</p> <p>4 DIMM non-FET Configurations: The buffer strength is programmable based upon the SDRAM load detected in all DIMM connectors.</p> <table border="0" style="margin-left: 40px;"> <thead> <tr> <th style="text-align: left;"><u>Value</u></th> <th style="text-align: left;"><u>Buffer Strength</u></th> </tr> </thead> <tbody> <tr> <td>00</td> <td>1X A and B</td> </tr> <tr> <td>01</td> <td>Reserved Invalid setting</td> </tr> <tr> <td>10</td> <td>2X A and B</td> </tr> <tr> <td>11</td> <td>3X B only</td> </tr> </tbody> </table>	<u>Value</u>	<u>Buffer Strength</u>	00	1X A and B	01	Reserved Invalid setting	10	2X A and B	11	3X B only
<u>Value</u>	<u>Buffer Strength</u>										
00	1X A and B										
01	Reserved Invalid setting										
10	2X A and B										
11	3X B only										



<p>31:30</p>	<p>MECC [7:0] Buffer Strength Control 2</p> <p>4 DIMM FET Configuration: This field sets the buffer strength for the MECC[7:0] path that is connected to DIMM2 and DIMM3. The buffer strength is programmable based upon the SDRAM ECC load detected in DIMM slots 2&3. This path is enabled when FENA is asserted (High) by the 82443GX.</p> <p>4 DIMM non-FET Configurations: This field should be programmed to the same value as MECC[7:0] Buffer Strength Control 1. This buffer strength is programmable based upon the SDRAM load detected in all DIMM connectors.</p> <table border="1" data-bbox="202 520 693 707"> <thead> <tr> <th>Value</th> <th>Buffer Strength</th> </tr> </thead> <tbody> <tr> <td>00</td> <td>1X A and B</td> </tr> <tr> <td>01</td> <td>Reserved Invalid setting</td> </tr> <tr> <td>10</td> <td>2X A and B</td> </tr> <tr> <td>11</td> <td>3X B only</td> </tr> </tbody> </table>	Value	Buffer Strength	00	1X A and B	01	Reserved Invalid setting	10	2X A and B	11	3X B only
Value	Buffer Strength										
00	1X A and B										
01	Reserved Invalid setting										
10	2X A and B										
11	3X B only										
<p>29:28</p>	<p>MECC [7:0] Buffer Strength Control 1</p> <p>4 DIMM FET Configuration: This field sets the buffer strength for the MECC[7:0] path that is connected to DIMM0 and DIMM1. The buffer strength is programmable based upon the SDRAM ECC load detected in DIMM slots 0&1. This path is enabled when FENA is de-asserted (Low) by the 82443GX.</p> <p>4 DIMM non-FET Configuration: The buffer strength is programmable based upon the SDRAM ECC load detected in all DIMM slots.</p> <table border="1" data-bbox="202 1015 693 1205"> <thead> <tr> <th>Value</th> <th>Buffer Strength</th> </tr> </thead> <tbody> <tr> <td>00</td> <td>1X A and B</td> </tr> <tr> <td>01</td> <td>Reserved Invalid setting</td> </tr> <tr> <td>10</td> <td>2X A and B</td> </tr> <tr> <td>11</td> <td>3X B only</td> </tr> </tbody> </table>	Value	Buffer Strength	00	1X A and B	01	Reserved Invalid setting	10	2X A and B	11	3X B only
Value	Buffer Strength										
00	1X A and B										
01	Reserved Invalid setting										
10	2X A and B										
11	3X B only										

13:12	<p>DQMA5 Buffer Strength</p> <p>This field sets the buffer strength for the DQMA5 pins.</p> <table border="0" data-bbox="244 323 693 508"> <thead> <tr> <th><u>Value</u></th> <th><u>Buffer Strength</u></th> <th></th> </tr> </thead> <tbody> <tr> <td>00</td> <td>1X</td> <td>A and B</td> </tr> <tr> <td>01</td> <td>Reserved</td> <td>Invalid setting</td> </tr> <tr> <td>10</td> <td>2X</td> <td>A and B</td> </tr> <tr> <td>11</td> <td>3X</td> <td>A only</td> </tr> </tbody> </table>	<u>Value</u>	<u>Buffer Strength</u>		00	1X	A and B	01	Reserved	Invalid setting	10	2X	A and B	11	3X	A only
<u>Value</u>	<u>Buffer Strength</u>															
00	1X	A and B														
01	Reserved	Invalid setting														
10	2X	A and B														
11	3X	A only														
11:10	<p>DQMA1 Buffer Strength</p> <p>This field sets the buffer strength for the DQMA1 pin.</p> <table border="0" data-bbox="244 685 693 870"> <thead> <tr> <th><u>Value</u></th> <th><u>Buffer Strength</u></th> <th></th> </tr> </thead> <tbody> <tr> <td>00</td> <td>1X</td> <td>A and B</td> </tr> <tr> <td>01</td> <td>Reserved</td> <td>Invalid setting</td> </tr> <tr> <td>10</td> <td>2X</td> <td>A and B</td> </tr> <tr> <td>11</td> <td>3X</td> <td>A only</td> </tr> </tbody> </table>	<u>Value</u>	<u>Buffer Strength</u>		00	1X	A and B	01	Reserved	Invalid setting	10	2X	A and B	11	3X	A only
<u>Value</u>	<u>Buffer Strength</u>															
00	1X	A and B														
01	Reserved	Invalid setting														
10	2X	A and B														
11	3X	A only														
9:8	<p>DQMB5 Buffer Strength</p> <p>This field sets the buffer strength for the DQMB5 pin.</p> <table border="0" data-bbox="244 1006 693 1191"> <thead> <tr> <th><u>Value</u></th> <th><u>Buffer Strength</u></th> <th></th> </tr> </thead> <tbody> <tr> <td>00</td> <td>1X</td> <td>A and B</td> </tr> <tr> <td>01</td> <td>Reserved</td> <td>Invalid setting</td> </tr> <tr> <td>10</td> <td>2X</td> <td>A and B</td> </tr> <tr> <td>11</td> <td>3X</td> <td>A only</td> </tr> </tbody> </table>	<u>Value</u>	<u>Buffer Strength</u>		00	1X	A and B	01	Reserved	Invalid setting	10	2X	A and B	11	3X	A only
<u>Value</u>	<u>Buffer Strength</u>															
00	1X	A and B														
01	Reserved	Invalid setting														
10	2X	A and B														
11	3X	A only														
7:6	<p>DQMB1 Buffer Strength</p> <p>This field sets the buffer strength for the DQMB1 pin.</p> <table border="0" data-bbox="244 1329 693 1514"> <thead> <tr> <th><u>Value</u></th> <th><u>Buffer Strength</u></th> <th></th> </tr> </thead> <tbody> <tr> <td>00</td> <td>1X</td> <td>A and B</td> </tr> <tr> <td>01</td> <td>Reserved</td> <td>Invalid setting</td> </tr> <tr> <td>10</td> <td>2X</td> <td>A and B</td> </tr> <tr> <td>11</td> <td>3X</td> <td>A only</td> </tr> </tbody> </table>	<u>Value</u>	<u>Buffer Strength</u>		00	1X	A and B	01	Reserved	Invalid setting	10	2X	A and B	11	3X	A only
<u>Value</u>	<u>Buffer Strength</u>															
00	1X	A and B														
01	Reserved	Invalid setting														
10	2X	A and B														
11	3X	A only														

5:4	<p data-bbox="209 204 534 227">DQMA[7:6,4:2,0] Buffer Strength</p> <p data-bbox="209 244 1040 267">This field sets the buffer strength for the DQMA[7:6], DQMA[4:2], and the DQMA[0] pins.</p> <table data-bbox="244 323 690 508"><thead><tr><th data-bbox="244 323 303 346"><u>Value</u></th><th data-bbox="400 323 546 346"><u>Buffer Strength</u></th></tr></thead><tbody><tr><td data-bbox="282 365 303 388">00</td><td data-bbox="400 365 530 388">1X A and B</td></tr><tr><td data-bbox="282 406 303 429">01</td><td data-bbox="400 406 690 429">Reserved Invalid setting</td></tr><tr><td data-bbox="282 447 303 470">10</td><td data-bbox="400 447 530 470">2X A and B</td></tr><tr><td data-bbox="282 488 303 512">11</td><td data-bbox="400 488 530 512">3X A and B</td></tr></tbody></table>	<u>Value</u>	<u>Buffer Strength</u>	00	1X A and B	01	Reserved Invalid setting	10	2X A and B	11	3X A and B
<u>Value</u>	<u>Buffer Strength</u>										
00	1X A and B										
01	Reserved Invalid setting										
10	2X A and B										
11	3X A and B										



Intel® 82443GX ERRATA

1. *SDRAM Suspend Refresh*

PROBLEM: This erratum may occur in Intel 440GX chipset platforms that implement suspend or Stop Clock (C3) states. Platforms that are affected are 4 DIMM desktop platforms using GCKE.

This platform requires the 440GX memory controller to stop the normal refresh and place the SDRAM in a self-refresh mode before the system transitions to one of these states. If the self-refresh trigger (SUSTAT1# signal asserted) occurs at the same time as an internally generated normal refresh request, the 440GX generates an incorrect GCKE and CSAx#CSBx# signal sequence to the SDRAM. The SDRAM is not placed in self-refresh mode and memory contents may be lost.

3 DIMM desktop platforms are not affected. 4 DIMM desktop platforms that do not use GCKE are also not affected.

IMPLICATION: The observed effect of the erratum is a system hang, although data loss or corruption is theoretically possible.

WORKAROUND:

APM BIOS workaround:

POS, POSCCL, POSCL, STR and C3 states

The workaround disables normal refresh prior to entering these states and before the 82443GX automatically generates the SDRAM self-refresh command. BIOS will re-enable normal refresh on exit from these states.

ACPI BIOS workaround (TBD):

RESOLUTION: Implement BIOS workaround.

Intel® 82443GX SPECIFICATION CLARIFICATIONS

1. *CKE Function with Registered DIMMs*

The stacking technology used for registered DIMMs prohibits the use of the CKE function. For registered DIMMs, components are stacked on top of one another. The stacked components are **physically** in the same row, but **logically** in separate rows. The stacked components connect all pins together, except for the CS# pin, in order to address components in different rows. Since the CKE pins for the components are connected together, and the components are **logically** in different rows, the CKE function is not supported.

2. *Memory Initialization with ECC Enabled*

For 82440GX systems using ECC memory, the memory must be initialized with ECC enabled (NBXCFG bits 31 through 24 and bits 7 and 8). Any ECC errors received during initialization should be ignored.

3. *Normal Refresh Enable*

When the user performs a soft reset, the PIIX4 will drive SUS_STAT1# to the 82443GX. This will force the 82443GX to switch to a suspend refresh state. When the BIOS attempts to execute cycles to DRAM, the 82443GX will not accept these cycles because it believes that it is in a suspend state

After coming out of reset the software must set the Normal refresh enable bit (bit 4, Power management control register Offset 7Ah) in the 82443GX before doing an access to memory.

4. *DCLKO State During POS/STR*

The state of DCLKO during POS/STR may be high or low. As a result, designs implementing POS/STR should move the CKBF component to the same VCC3 plane as the 82443GX component.



Intel® 82443GX DOCUMENTATION CHANGES

1. *Correction to the 82443GX Alphabetical BGA Pin List (Table 5-1)*

Table 5-1 has pin MAB14 incorrectly referenced as AE22. The correct pin location on the 82443GX is AE23.



United States and Canada

Intel Corporation
Robert Noyce Building
2200 Mission College Boulevard
P.O. Box 58119
Santa Clara, CA 95052-8119
USA
Phone: (800) 628-8686

Europe

Intel Corporation (U.K.) Ltd.
Pipers Way
Swindon
Wiltshire SN3 1RJ

UK

Phone:

England (44) 1793 403 000
Germany (49) 89 99143 0
France (33) 1 4571 7171
Italy (39) 2 575 441
Israel (972) 2 589 7111
Netherlands (31) 10 286 6111
Sweden (46) 8 705 5600

Asia Pacific

Intel Semiconductor Ltd.
32/F Two Pacific Place
88 Queensway, Central
Hong Kong, SAR
Phone: (852) 2844 4555

Japan

Intel Kabushiki Kaisha
P.O. Box 115 Tsukuba-gakuen
5-6 Tokodai, Tsukuba-shi
Ibaraki-ken 305
Japan
Phone: (81) 298 47 8522

South America

Intel Semicondutores do Brazil
Rua Florida 1703-2 and CJ22
CEP 04565-001 Sao Paulo-SP
Brazil
Phone: (55) 11 5505 2296

For More Information

To learn more about Intel Corporation, visit our site
on the World Wide Web at www.intel.com

Intel around the world